


## LINING UP THE R.A.T. MARKERS

### HOW TO LINE UP MARKERS




Draw a line from the centre of the disc to the outside with a pencil or a marker pen. Note: Try and draw the line as thin as possible or use the AWI grinding template for best results.

### HANG PENDULUM

Put the cutter on your cutter pendulum and hang from the pendulum hanging point on your grinder.




### LINE UP R.A.T. MARKERS



Hang your cutter where you want to finish on the disc. Line up the R.A.T. Markers along the radius line that was drawn earlier.

### FINAL STEP

Once the R.A.T. Markers are in line with the radius line, tighten the pendulum nut so its locked into the position.



Scan for more information

